

Hawkeye & New KSM Licensing

08/12/2022

Customers using Hawkeye 5.2.2 and previous versions will not be able to Sync with the license servers, purchase new licenses and renew their licenses after August 12th 2022. Utilizing the patch procedure below to patch Hawkeye Server 5.2.2 will allow full license operations. If you have Hawkeye 5.x version before version 5.2.2, you will be required to upgrade to version 5.2.2, and then apply a patch to perform any licensing operations. If you are not performing any licensing operations, there is no need to patch at this time.

Below is the link to the patch for Hawkeye 5.2.2: *ixia-LicenseServerPlus-5.50.0-28.el7.i686.rpm*

<https://ixiapublic.s3-us-west-2.amazonaws.com/hawkeye/downloads/ixia-LicenseServerPlus-5.50.0-28.el7.i686.rpm>

Utilize a file transfer program to move the downloaded .rpm file into the Hawkeye server's /tmp directory after the server is upgraded to 5.2.2. then perform the following commands:

Change working directory to /tmp

```
[Hawkeye-Server ~]# cd /tmp
```

Run the local install of the license patch.

```
[Hawkeye-Server tmp]# yum localinstall ixia-LicenseServerPlus-5.50.0-28.el7.i686.rpm
```

```
...
```

```
Complete
```



Restart services for changes to take effect

```
[Hawkeye-Server tmp]# hawkeyeServices
```

...

Confirm License Server has been updated to 5.50.0.28

```
[Hawkeye-Server tmp]# cat /opt/ixia/licenseserverplus/licensing.version  
5.50.0.28
```

Learn more at: www.keysight.com

For more information on Keysight Technologies' products, applications or services, please contact your local Keysight office. The complete list is available at: www.keysight.com/find/contactus

